KNEE BRACE SIZING

ADULT

BRACE SIZE	SMALL/MEDIUM	LARGE/X-LARGE
INCHES	10 1/4 - 11 3/4	12 - 12 7/8
CENTIMETERS	26.04 - 29.85	30.48 - 32.70

GERM

BRACE SIZE	SMALL/MEDIUM	LARGE/X-LARGE
INCHES	10 1/4 - 11 3/4	12 - 12 7/8
CENTIMETERS	26.04 - 29.85	30.48 - 32.70

HOW TO MEASURE KNEE BRACE SIZE

HOW TO SIZE THE CELL

Caliper measurement

Authorized dealers will simply use an Asterisk Caliper to measure the width of a knee. The width of the knee, matched up to the Asterisk sizing scale (found on order forms) will determine the correct size of brace.

1. Measurement should be taken straight across the knee in a standard weight bearing position, Slide caliper against the knee.



Read measurement
at the edge (not in opening).



CALIPER MEASUREMENT CHART

3 5/8"- 4"	4"- 4 3/8"	4 3/8"- 4 5/8"	4 5/8"- 4 7/8"	4 7/8"- 5 1/4"
SM	MED	LG	XL	XXL

measurement in inches

Circumference measurement

To ensure a proper fit, circumference measurements should be taken directly on the skin with the leg straightened, using a soft tape measure. (If a soft tape measure is not available, a piece of string or yarn may be used to calibrate the leg's diameter, then measured against a hard tape measure.) Paper tape measures are available at no charge.

1. Locate the middle of the kneecap and measure around the leg. Measurements should be taken directly on the skin with a straight leg.



CIRCUMFERENCE MEASUREMENT CHART

13"-13 7/8"	14"-14 7/8"	15"-15 7/8"	16"-16 7/8"	17"-18 1/4"
SM	MED	LG	XL	XXL

measurement in inches